

e 115. Soot on the Second-Stage Impeller Blades and Flowpath

Honeywell Report, Figure 115